


# SH420/386TC-U26 - SH420 Tunnel thruster, U26

Spare parts (valid from 2017-09-29)



#	Description	Product
1	Propeller	50 1270**
2	Propeller key	50 1241 - Kile prop.aksel SP550TC
3	Propeller washer	50 1181 - Skive
4	Locknut	50 1260 - Låsemutter
5	Anode	50 1180 A - Alu anode SP420/550HYD
6	Oil drain screw with gasket	50 1220 - Oljeplugg
7	Gasket (between gearleg and tunnel)	50 1312 - Pakning mot tunnel SP550TC
8	Gearleg bolt	50 1080 - Skrue M16 x 100 6kt
9	Complete gearleg	50 0600 - Gearhus montert SP550
10	O-ring seals in motor bracket	50 1340 - O-ring
11	Complete motor bracket	[Archived] 50 0500 - *Motorbrakett maskinert SP550
12	Oil hose with hose clamps	20 0400 - Olje slange 2,5m med 3klemmer 327034-12
13	Oil container with bracket	20 0300 - Olje beholder med klemme
14	Complete flexible coupling	50 1450 HYD - Flek.kobling SP550TC SAEB-SAEC
15	Adaptor plate (U-motors only)	5021301 - Adapterplate maskinert SP550
16	Hyd. Motor options:	[Archived] 000-0096-76 - Eagle repaire Ultra Classic
16a	U-26	72100/U-26 - Hydraulikk motor 26ccm (G26)
16b	U-29	72100/U-29 - Hydraulikk motor 29ccm ultra
16c	U-33	72100/U-33 - Hydraulikk motor 33ccm ultra
16d	U-37	72100/U-37 - Hydraulikk motor 37ccm ultra
16e	BA 32	72100/BA 32
17	Hyd. Motor assembly options:	[Archived] 000-0096-76 - Eagle repaire Ultra Classic
17a	SH420 motor, U-26, complete, w/flex. Coupling	502126UL2 - Hyd. motor mont.SP550-26ccm U
17b	SH420 motor, U-29, complete, w/flex. Coupling	502129UL2 - Hyd. motor mont.SP550-29ccm U
17c	SH420 motor, U-33, complete, w/flex. Coupling	502133UL2 - Hyd. motor mont.SP550-33ccm U
17d	SH420 motor, U-37, complete, w/flex. Coupling	502137UL2 - Hyd. motor mont.SP550-37ccm U
17e	SH420 motor, BA 32, complete, w/flex. Coupling	502132UL - Hyd.motor SH420-32ccm BentAxis

The installer alone has responsibility for the installation of the spare parts. Side-Power only warranty the spare parts supplied only.

The information given in the document was correct at the time it was published. However, Sleipner Motor AS can not accept liability for any inaccuracies or omissions it may contain. Continuous product improvement may change the product specifications without notice. Therefore, Sleipner Motor AS can not accept liability for any possible differences between product and document.